

IMPORTANT SAFETY RECALL

Porter-Cable, Delta Shopmaster, DeVilbiss, Craftsman (Canada) and Husky Air Compressors

The air compressor motor can overheat, posing a fire hazard.

The following air compressors are potentially affected:

Model Number	Brand	Tank	Tank Color	Date Range
C2000-WK	Porter-Cable	6 gal. pancake	Red	1/2004 - 5/2004
C3001	Porter-Cable	4 gal. stacked	Red	1/2004 - 7/2004
CP503	Delta Shopmaster	12 gal. horizontal	Gray	6/2002 - 3/2003
CP503-1	Delta Shopmaster	12 gal. horizontal	Gray	5/2003 - 3/2004
HFAC 3030	DeVilbiss Impact Series	3 gal. horizontal	Blue	1/2003 - 7/2004
Y6010-WK	Husky	25 gal. vertical	Red	2/2003 - 9/2003
Y6010-WK-1	Husky	25 gal. vertical	Red	7/2003 - 9/2003
Y6020-WK	Husky	25 gal. vertical	Red	5/2003 - 3/2004
919.72412	Craftsman (Sold only in Canada)	15 gal. horizontal	Red	8/2001 - 8/2003
919.724121	Craftsman (Sold only in Canada)	15 gal. horizontal	Red	9/2002 - 5/2005
919.724122	Craftsman (Sold only in Canada)	15 gal. horizontal	Red	5/2004 - 1/2005
919.72413	Craftsman (Sold only in Canada)	15 gal. vertical	Red	1/2004 - 3/2005



Mod.	ABC0000-0		Discharge into/Against
Gal.	00	0	00.0 CFM Air Delivery (SCFM) Discharge Against (SCFM) (1/4" dia. pipe and standard)
Electr.	120V/240V/15A/8A/60HZ/1PH		0.0 SCFM @ 40PSI 0.0 SCFM @ 90PSI
Pump / Bomba / Pompe	Max. Pres. / Pres. Max.	Max. RPM / RPM Max. / Tr.M.	
-AC-0000	000 PSI	0000	CL-0000
CALIFORNIA CODE 482 (1) (2) NON-218  COMPLIES TO STANDARD NO. HACA 100		SER. NO. 9999999999	WG
DeVilbiss Air Power Company Jackson, Tennessee 38301-9615 1-800-888-2468			
		PATENT PENDING	01-23-06 Month Day Year

Could also be shown as: 2006-4-21
Year Week Plant

If your compressor is affected, UNPLUG AND STOP USING IT IMMEDIATELY, and call toll free

1-866-220-5627

between 8 a.m. and 5 p.m., Eastern Time, Monday through Friday, or visit
www.porter-cable.com or www.devap.com, for information about a free repair.